Nantucket Electric Company 2004 Results of Service Quality Plan D.T.E. 05-22 Supplement Section 3 Attachment F Page 1 of 1

2004 Poor Performing Circuits													
/«	şē 3 ₁₁ 56	Tamas							\$\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\				
101L6	Bay State South	Nantucket	3.12	135.31	√	√			I √				This feeder has had three tree related interruptions that have significantly increased the SAIFI index. Portion of the mainline circuit path is lined with historic elm trees which the Town has allowed only minimum trimming. Automatic reclosing will be added to the circuit protection scheme to reduce the impact of transient limb and branch contacts. Efforts will continue to secure approval to remove hazard trees and limbs whenever identified.